



35. B Floor West Mech Rm - General view of fireproofing debris on top of HVAC duct above suspended ceiling




36. B Floor East Mech Rm - General view of delaminated fireproofing off beam in mechanical room





37. B Floor East Mech Rm - General view of fireproofing debris on top of large electrical panel



38. B Floor East Mech Rm - Close-up view of fireproofing debris on top of large electrical panel



39. B Floor East Mech Rm - View of fireproofing debris on top of breaker box